

# W-22AL

## Silicone


Self-Adhesive Gasket Installation Instructions

# KNC

17'2"

20'4"

25'



Anti-ligature

**Note: Adhesive seals have a limited shelf life. Products should be installed as soon as possible.**



## Preparation

Frame must be clean, dry and free of dust, oil, grease, etc. Clean with alcohol wipe or suitable cleaner that does not leave residue. Paint must be dry/cured. High gloss finishes may require scuffing with Scotchbrite pad to facilitate proper adhesion.

**Note: Some frame manufacturers apply light wax to hollow metal frames. Remove wax with appropriate wax remover. Frame must be above 10°C or 50°F.**

## Installation

1. Measure and pre-cut gasket to suit head and jamb lengths. Do not apply in one continuous piece.
2. Remove protective backing 12-24" at a time, and apply gasket according to illustrations.  
**Latch side jamb and head:** Apply to frame, per Figure A.  
**Hinge side jamb:** Apply to strike, per Figure B.
3. Repositioning is not recommended, but if required should be done immediately: Gently remove gasket, reposition and apply pressure along the full length of the gasket. Full adhesive strength will develop over 24-48 hours.



Silicone Self-Adhesive Gasket  
Smoke, light and sound control  
Unaffected by fungus and mildew  
Temperature range: -110°F to +400°F (-80°C to +204°C)  
Provides little resistance to door closing devices  
Adhesive shelf life, when stored at room temperature, 6 months.  
Applications with 90 minute wood veneered steel frames.



KN CROWDER  
Weatherstrip / Threshold / Auto Door Bottom / Astragal  
CERTIFIED TO: CAN/ULC S104 NFPA525 UL10B  
See Intertek's directory of Building Products for information.





Intertek's directory of Building Products

# W-22AL

## Silicone



Self-Adhesive Gasket Installation Instructions

# KNC

17'2"

20'4"

25'



Anti-ligature

**Note: Adhesive seals have a limited shelf life. Products should be installed as soon as possible.**



## Preparation

Frame must be clean, dry and free of dust, oil, grease, etc. Clean with alcohol wipe or suitable cleaner that does not leave residue. Paint must be dry/cured. High gloss finishes may require scuffing with Scotchbrite pad to facilitate proper adhesion.


**Note: Some frame manufacturers apply light wax to hollow metal frames. Remove wax with appropriate wax remover. Frame must be above 10°C or 50°F.**

## Installation


1. Measure and pre-cut gasket to suit head and jamb lengths. Do not apply in one continuous piece.
2. Remove protective backing 12-24" at a time, and apply gasket according to illustrations.  
**Latch side jamb and head:** Apply to frame, per Figure A.  
**Hinge side jamb:** Apply to strike, per Figure B.
3. Repositioning is not recommended, but if required should be done immediately: Gently remove gasket, reposition and apply pressure along the full length of the gasket. Full adhesive strength will develop over 24-48 hours.



Silicone Self-Adhesive Gasket  
Smoke, light and sound control  
Unaffected by fungus and mildew  
Temperature range: -110°F to +400°F (-80°C to +204°C)  
Provides little resistance to door closing devices  
Adhesive shelf life, when stored at room temperature, 6 months.  
Applications with 90 minute wood veneered steel frames.



KN CROWDER  
Weatherstrip / Threshold / Auto Door Bottom / Astragal  
CERTIFIED TO: CAN/ULC S104 NFPA525 UL10B  
See Intertek's directory of Building Products for information.





Intertek's directory of Building Products